

**FIG. 1**

FIG. 2






FIG. 2




**FIG. 3**

ROUTINE 400  
(STEP 304, FIG. 3)




**FIG. 4**



**FIG. 5**

ROUTINE 600  
(STEP 514, FIG. 5)



**FIG. 6**

ROUTINE 700  
(STEP 614, FIG. 6)





FIG. 7

ROUTINE 800  
(STEP 516, FIG. 5)



**FIG. 8**






FIG. 9




FIG. 12




FIG. 10




FIG. 13




FIG. 11




FIG. 14




FIG. 15




FIG. 18




FIG. 16




FIG. 19




FIG. 17




FIG. 20




FIG. 21






FIG. 22

ROUTINE 2300



**FIG. 23**



**FIG. 24**